



- 1 Turn power off at electrical box.
- Ground the universal mounting bracket to junction box and transformer wire.
- Connect the black and white wires of transformer to the hot and neutral wires in Jbox.
- Insert transformer into Jbox.
- Connect secondary low voltage wires of transformer to universal mounting bracket connector wires.
- Position universal mounting bracket toward Jbox and secure universal mounting bracket directly to Jbox using screws from accesory bag.
- 7 Slide decorative canopy cover over universal mounting bracket and secure canopy to universal mounting bracket using threaded decorative collar ring.
- Place the canopy cover over the universal mounting bracket and screw cap onto the threaded universal mounting bracket post.


COMPONENTS INCLUDED IN CANOPY KIT



Universal Mounting Bracket



Canopy



Transformer



Accesory bag

Collar Ring